

12/8/99

NOTE: THIS SERVICE NEED TO
BE TRANSFERED FROM
888888 TO 88887
ONCE INSULATOR
SITUATION IS RESOLVED

EDDIE PERRY,

WHEN 824 WAS
TIED OVER TO
THE PLASTIC MAIN
WAS THE EXISTING
INSULATOR BONDED
IF NOT I HAVE
AN ISOLATED SECTION
AND NO WAY OF
MONITORING IT

1/2 S.

1.0.

12/13/99

PER
MIKE DELANEY

A1 - tested EXT
3/4" C/W Service.
100 PSI 3-19-90
E.P.

SERVICE LOCATION RECORD

K	LOC	ACCT	SUB	WORK ORDER NO	CITY NO	KEY NO	GRID NO	CP NO	PROJECT NO
1	7256202	4897	824	47783	42065	A129			

