

LOCATION 1119 Sunshine Uniform - Jenkins Rd. CITY OASTONIA  
BETWEEN Poplar St. STREET & Jenkins Rd. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG.	2"	CFW	30'	9-27-94		
MAIN TO PROP. LINE						
PROP. LINE TO BLDG.						

ENTERS: 1119 BRANCHED INTO:  
TAP SIZE: PRESSURE \_\_\_\_\_ P.S.I. \_\_\_\_\_ INCHES W.C. LOCATION


PRESSURE TEST: @ \_\_\_\_\_ psi For \_\_\_\_\_ Hrs. By \_\_\_\_\_

MAIN-SIZE \_\_\_\_\_ C.I. \_\_\_\_\_ BARE STEEL \_\_\_\_\_ COATED STEEL \_\_\_\_\_ PLASTIC \_\_\_\_\_ YEAR INSTALLED \_\_\_\_\_

DEPTH: Ft. In. LOCATION

"A" P/S READING \_\_\_\_\_ TOTAL ANODES 1\* \_\_\_\_\_ 17\* \_\_\_\_\_ L.R. # \_\_\_\_\_

REMARKS: 143 - Form Attached. Removed 30' 2" CFW Pipe & Replaced with New 2" CFW Pipe - Installed Split Fitting & stopped line off until Tank Removal & Grading Complete. Then Reinstalled Pipe. Tested 2" CFW Service Pipe 15 min. Before Installings. Pipe badly pitted where coating had been knocked off previously when concrete pithers poured



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead - Red New Service	S	
P/S Pipeline Lead - White Existing Main	E	

ENG. DEPT. USE ONLY