

LOCATION N. 106 Belvedere CITY Estonia
BETWEEN Craig Ave STREET & Davis STREET

| | SIZE | TYPE | LENGTH | INSTALLED | RETIRED | RENEWED |
|---------------------|------------|----------|------------|-----------|-------------------------|---------------|
| MAIN TO BLDG. | <u>3/4</u> | <u>D</u> | <u>54'</u> | | | <u>5-5-84</u> |
| MAIN TO PROP. LINE | <u>3/4</u> | <u>D</u> | <u>5'</u> | | <u>70' of 3/4" BARE</u> | |
| PROP. LINE TO BLDG. | <u>3/4</u> | <u>P</u> | <u>49'</u> | | | |

ENTERS: 106 N. Belvedere BRANCHED INTO: 0

TAP SIZE: 3/4" S. PRESSURE 20 P.S.I. INCHES W.C. LOCATION


PRESSURE TEST: @ 100 psi For 1 1/4 Hrs. By EP

MAIN-SIZE 3/4 C.I. BARE STEEL ☒ COATED STEEL PLASTIC YEAR INSTALLED 1958

DEPTH: Ft. In. LOCATION

"A" P/S READING 6 TOTAL ANODES 1# 1 17# L.R. #

REMARKS:



| Test Station | | |
|--|--------------------------|-------|
| Reading & Location | Lead | Volts |
| P/S Pipeline Lead - Red New Service | <u>S</u> <u>0.434</u> | |
| P/S Pipeline Lead - White Existing Main | <u>E</u> | |

ENG. DEPT. USE ONLY