

LOCATION 1141 Crowders Woods Dr. CITY SANTONIA  
BETWEEN CANSON Rd. STREET & JANEE CT. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	<u>5/8</u>	<u>PLASTIC</u>	<u>73'</u>	<u>B-23-02</u>		
MAIN TO PROP LINE	<u>5/8</u>	<u>PLASTIC</u>	<u>13'</u>			
PROP LINE TO BLDG	<u>5/8</u>	<u>PLASTIC</u>	<u>63'</u>			

ENTERS 1141 BRANCHED INTO 0

TAP SIZE 3/4 PRESSURE 60 PSI \_\_\_\_\_ INCHES W.C. LOCATION 175' N of C of Canson Rd.

PRESSURE TEST @ 100 PSI FOR 1/4 HRS BY RL

MAIN-SIZE 4" C I \_\_\_\_\_ BARE STEEL \_\_\_\_\_ COATED STEEL \_\_\_\_\_ PLASTIC ☒ YEAR INSTALLED 2002

DEPTH 3 FT 0 IN LOCATION 19' W of C of Crowders Woods Dr.

"A" P/S READING PLASTIC N/A TOTAL ANODES 1# \_\_\_\_\_ 17# \_\_\_\_\_ LR # \_\_\_\_\_

REMARKS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead - Red New Service	<u>S</u>	<u>Reverse</u>
P/S Pipeline Lead - White Existing Main	<u>E</u>	<u>PLASTIC</u>