

LOCATION 1518 Crowdens Woods Dr. CITY BANTONIA
 BETWEEN Shady OAK Trail STREET & Laura Woods Dr. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	<u>3/4</u>	<u>Plastic</u>	<u>97'</u>	<u>1-27-00</u>		
MAIN TO PROP LINE	<u>3/4</u>	<u>Plastic</u>	<u>5'</u>			
PROP LINE TO BLDG	<u>3/4</u>	<u>Plastic</u>	<u>92'</u>			


ENTERS 1518 BRANCHED INTO 0
 TAP SIZE 1/2 PRESSURE 60 PSI INCHES WC LOCATION 72' N of C of Shady OAK Trail

PRESSURE TEST @ 100 PSI FOR 1/4 HRS BY RL
 MAIN SIZE 2" C I BARE STEEL COATED STEEL PLASTIC ✓ YEAR INSTALLED 1998

DEPTH 3 FT 6 IN LOCATION 24' E of C of Crowdens Woods Dr.

"A" P/S READING Plastic N/A TOTAL ANODES 1# 0 17# 0 LR 00058482

REMARKS



Test Station		
Reading & Location	Lead	Volts*
P/S Pipeline Lead Red	<u>S</u>	<u>Rose</u>
New Service		
P/S Pipeline Lead White	<u>E</u>	<u>Plastic</u>
Existing Main		