

MAIN REPAIR SHEET

SHEET NO. 1 OF 1

CITY CASTONIA		STREET OR BLOCK NO. 700		DATE 5/29/74	WORK ORDER NO. 115008	CITY NO. 700	KEY NO. 56	GRID NO. A3-31	CASE NO. 19
PIPE SIZE 3" New	MAIN DEPTH 48"	MAIN TO CURB 48"	CONDITION PAIR	YEAR INSTALLED 1955	FOREMAN J. H. H.		NONE SUPERVISOR		
TYPE OF REPAIR REPAIR		SOURCE OF DISCOVERY OUTSIDE CONSULTANT		LOCATION OF LEAK PIPE		CAUSE OF LEAK CORROSION		COATING COATED	
WC PE	MFG STYLE	SIZE SIZE	<input checked="" type="checkbox"/> COMPANY PERSONNEL	<input type="checkbox"/> VALVE	<input type="checkbox"/> DAMAGE BY OUTSIDE FORCE	<input checked="" type="checkbox"/> BARE			
KIND RENEW	<input checked="" type="checkbox"/> MAIN-SERVICE	<input type="checkbox"/> DAMAGE BY OUTSIDE FORCE	<input type="checkbox"/> FITTING	<input type="checkbox"/> LEAKING BELL JOINT	<input type="checkbox"/> CAST IRON				
MAIN SERVICE	DATE OF DETECTION 3-6-74	<input type="checkbox"/> CUSTOMER	<input type="checkbox"/> DRIP	<input type="checkbox"/> CONSTRUCTION DEFECT	CATHODIC PROTECTION PROTECTED				
OTHER		<input type="checkbox"/> PUBLIC	<input type="checkbox"/> REGULATOR	<input type="checkbox"/> MATERIAL FAILURE	<input type="checkbox"/> PROTECTED				
		<input type="checkbox"/> OTHER	<input type="checkbox"/> TAP CONNECTION	<input type="checkbox"/> OTHER	<input checked="" type="checkbox"/> UNPROTECTED				
OTHER				GRADE OF LEAK					
				<input type="checkbox"/> I <input checked="" type="checkbox"/> II <input type="checkbox"/> III					

ADDRESS: 711 E. FRANKLIN BLVD.

