

LOCATION 917 Harper Rd. CITY Corona
BETWEEN Union Rd STREET & STREET


| | SIZE | TYPE | LENGTH | INSTALLED | RETIRED | RENEWED |
|---------------------|------------|----------|-----------|-----------|---------------|---------|
| MAIN TO BLDG. | <u>3/4</u> | <u>P</u> | <u>8'</u> | | <u>5-9-97</u> | |
| MAIN TO PROP. LINE | | | | | | |
| PROP. LINE TO BLDG. | | | | | | |

ENTERS: _____ BRANCHED INTO: _____
TAP SIZE: _____ PRESSURE _____ PSI _____ INCHES W.C. LOCATION _____

PRESSURE TEST: @ _____ PSI FOR _____ HRS. BY _____
MAIN-SIZE 3/4 C.I. _____ BARE STEEL _____ COATED STEEL _____ PLASTIC ☒ YEAR INSTALLED 1991
DEPTH: 3 FT. 0 IN. LOCATION _____

"A" P/S READING P TOTAL ANODES 1# 17# L.R. # _____

REMARKS: _____



| Test Station | | |
|--|----------|----------------|
| Reading & Location | Lead | Volts |
| P/S Pipeline Lead - Red New Service | <u>S</u> | <u>Retired</u> |
| P/S Pipeline Lead - White Existing Main | <u>E</u> | |

ENG. DEPT. USE ONLY