

LOCATION 1201 Lansdowne Dr. CITY Gastonia  
BETWEEN Montrose Dr. STREET & Hollandale Dr. STREET

	SIZE	TYPE	LENGTH	INSTALLED	RETIRED	RENEWED
MAIN TO BLDG	<u>3/4"</u>	<u>P</u>	<u>83'</u>	<u>12-11-2000</u>		
MAIN TO PROP LINE	<u>3/4"</u>	<u>P</u>	<u>3'</u>	<u>"</u>		
PROP LINE TO BLDG	<u>3/4"</u>	<u>P</u>	<u>80'</u>	<u>"</u>		

ENTERS 1201 Lansdowne Dr. BRANCHED INTO 2

TAP SIZE 1/2" PRESSURE 60 PSI \_\_\_\_\_ INCHES W.C. LOCATION 58' West of


PRESSURE TEST @ 100 PSI FOR 1/4 HRS BY D. Revels center of Hollandale

MAIN-SIZE 2" C I \_\_\_\_\_ BARE STEEL \_\_\_\_\_ COATED STEEL \_\_\_\_\_ PLASTIC ☒ YEAR INSTALLED 1998

DEPTH 3' FT 6" IN LOCATION 21' south of center of Lansdowne Dr.

"A" P/S READING N/A TOTAL ANODES 1# 0 17# 0 I.R. # 0115240.3

REMARKS. new plastic service



Test Station		
Reading & Location	Lead	Volts
P/S Pipeline Lead - Red New Service	<u>S</u>	<u>plastic</u>
P/S Pipeline Lead - White Existing Main	<u>E</u>	<u>riser</u>